

**FITNESS CERTIFICATE BY THE ASSISTANT ENGINEER**  
(See GO(Rt) 1304/74/PWD dt 11.11.1974)

1	Name of Officer	ELDO SIMON, Assistant Engineer, LID & EW Section, Anthikad Grama Panchayat
2	Name of School	SREE SAI VIDYA PEEDHOM SENIOR SECONDARY SCHOOL
3	Location with Name of Educational District with Sub district.	MANGATTUKARA, ANTHIKKAD P.O
4	Classification of Building as Specified in Column 4 of the application for Fitness Certificate and Size	RCC BUILDING
5	Period for which Certificate issued	For the Academic Year 2025-2026
6	Nature of Defect if any	<p align="center"><b>Not Noticed</b> <b>at the time</b> <b>of inspection</b></p> <p>6.50 X 6.50 - 15 ROOMS 16.62 X 6.50 - 1 LAB 3.00 X 6.50 - 1 STAFF ROOM 10.10 X 12.38 -1 LIBRARY ROOM (GI SHEET)</p>
a)	Foundation and Basement	
b)	Superstructure	
c)	Doors and Windows	
d)	Woodwork Wrought-& Putup	
e)	Roof	
f)	Flooring	
g)	Miscellaneous (Cracks etc..)	
7	Any Major Defects Noticed which will render the building unsafe.	Yes; Details discribed below has Conditions 1
8	Whether Maintenance work have been done properly	Yes
9	Whether the structure is Sound or Not For conducting Classes	Structure is fit under normal wind and weather condition

Note: 1) The Stability of Structure should be examined also with reference to location attitude, intensity of wind, exposure to flood etc.  
2) Any Additional observations if indeed necessary for the certificate may be furnished separately with the certificate.

Certified that the School was inspected by me on 11-08-2025 and found to be **FIT** to conduct classes  
in the Academic Year 2025-26 for reason stated above.

CONDITIONS

1) The newly Constructed portions of the school building which have no building number yet to be applied for Occupancy  
as soon as possible. ✓

Place : 11-08-2025  
Date : ANTHIKAD



Signature

**ASSISTANT ENGINEER**  
**L.S.G.D. SECTION ANTHIKAD**  
**THRISSUR-680641**